



Navhouse Corporation

10 Loring Drive

Bolton, Ontario, Canada L7E 1J9

905-857-8102

Contact:

Julie D'Ettorre Customer Service Manager

Repair/Overhaul Capability List 2017			
Part Number	System	Desc	OEM
686660-1	LN33 Inertial Navigation Unit	LN33	Litton
10089774-xxx	Honeywell Power Supply	HG P/S	Honeywell
F+W-11702-100	Angle of Attack Indicator	AOA	Rosemount
30G1	Angle of Attack Indicator	AOA	Rosemount
30G2	Angle of Attack Indicator	AOA	Rosemount
30G3	Angle of Attack Indicator	AOA	Rosemount
948312-6-1	Central Air Data Computer	CADC	Air Research
2100756-3-1	Central Air Data Computer	CADC	Honeywell
19005-1A	Displacement Gyro	Gyro	Bendix
19005-1B	Displacement Gyro	Gyro	Bendix
19005-1C	Displacement Gyro	Gyro	Bendix
19005-2C	Displacement Gyro	Gyro	Bendix
140070-01-01	Displacement Gyro	Gyro	Lear Siegler
124623-01-13 / -14	Displacement Gyro	Gyro	Bendix
CN790/APS88A	Displacement Gyro	Gyro	Navair
110801-100	G Warning Unit	GWU	Bendix
304580-2	Rate Gyro	Gyro	Bendix
64585-303	Rate Gyro	Gyro	Northrop
79148-302	Rate Gyro	Gyro	Bendix
GG 2479AA01	Rate Gyro	Gyro	Honeywell
GG 2479AB01	Rate Gyro	Gyro	Honeywell
GG79A41	Rate Gyro	Gyro	Sperry
GRG5A-5B	Rate Gyro	Gyro	Sperry
13120	Rate Gyro	Gyro	Condor
20100	Rate Gyro	Gyro	Dynascience

Repair/Overhaul Capability List 2017			
Part Number	System	Desc	OEM
20110	Rate Gyro	Gyro	Condor
204-56237-5	AFC Interface	AFC	Boeing